




Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 1 of 8

PHOTOS OF TESTING

- Conducted emission test





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 2 of 8

- Radiated emission test (below 30MHz TX & Standby)





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 3 of 8

- Radiated emission test (below 1GHz TX & Standby)





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 4 of 8

- Radiated emission test (above 1GHz TX & Standby)





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 5 of 8

- Radiated emission test (above 1GHz TX & Standby)





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 6 of 8

- Radiated emission test (below 1GHz Link)





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 7 of 8

- Radiated emission test (above 1GHz Link)





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12053104 Photo Page: 8 of 8

- Radiated emission test (above 1GHz TX & Standby)

