

Response to TCB Findings

Test setup photos show an external antenna. It appears the device is using an internal antenna only. Please clarify.

The larger item with the external antenna is not the transmitter under test, but was used as support equipment to pass traffic. The transmitter under test is the small item to the right and uses an internal antenna mounted on the PCB.

On Pg 7 of the report, the first plot shows an emission after the 928MHz band-edge marker. Has this emission met the 15.209 or 50 dB below fundamental limit? Please clarify.

The emission to the right of the band-edge marker is ambient noise and not an emission from the transmitter under test.