

Prüfbericht - Nr.: 16004959 001

Test Report No.:

Seite 13 von 16

Page 13 of 16

6 Photographs of the Test Set-Up

Photograph 1: Set up for Conducted Emission on AC Mains




Prüfbericht - Nr.: 16004959 001

Test Report No.:

Seite 14 von 16

Page 14 of 16

Photograph 2: Set-up for Radiation Measurement Below 1GHz



Prüfbericht - Nr.: 16004959 001

Test Report No.:

Seite 15 von 16

Page 15 of 16

Photograph 3: Set-up for Radiation Measurement Above 1GHz

