


Prüfbericht - Nr.: 16001891 001
Test Report No.:

Seite 12 von 14
Page 12 of 14

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Radiation Measurement Below 1GHz



Prüfbericht - Nr.: 16001891 001
Test Report No.:

Seite 13 von 14
Page 13 of 14

Photograph 2: Set-up for Radiation Measurement Above 1GHz

