

Prüfbericht - Nr.: 16004375 001

Test Report No.:

Seite 14 von 17

Page 14 of 17

6 Photographs of the Test Set-Up


Photograph 1: Set up for Conducted Emission on AC Mains



Prüfbericht - Nr.: 16004375 001
Test Report No.:

Seite 15 von 17
Page 15 of 17

Photograph 2: Set-up for Radiation Measurement Below 1GHz



Prüfbericht - Nr.: 16004375 001
Test Report No.:

Seite 16 von 17
Page 16 of 17

Photograph 3: Set-up for Radiation Measurement Above 1GHz

