

6 Photographs of the Test Set-Up


Photograph 1: Set-up for Radiation Measurement below 1GHz



Prüfbericht - Nr.:
Test Report No.:

16011141 001

Seite 29 von 31
Page 29 of 31



Prüfbericht - Nr.:
Test Report No.:

16011141 001

Seite 30 von 31
Page 30 of 31

Photograph 2: Set-up for Radiation Measurement above 1GHz

