

Prepared by: LabTest Certification Inc.
Date Issued: February 15, 2013
Project No: 11239

Client:
Report No.:
Revision No.:

SST Wireless Inc.
11239-1E
0

APPENDIX C: Test setup photos

- Test configuration for Field Strength measurement, installed in Tire1




Prepared by: LabTest Certification Inc.
Date Issued: February 15, 2013
Project No: 11239

Client:
Report No.:
Revision No.:

SST Wireless Inc.
11239-1E
0

- Test configuration for Field Strength measurement, installed in Tire2



Prepared by: LabTest Certification Inc.
Date Issued: February 15, 2013
Project No: 11239

Client:
Report No.:
Revision No.:

SST Wireless Inc.
11239-1E
0

- Test configuration for Field Strength measurement, installed in Tire3




Prepared by: LabTest Certification Inc.
Date Issued: February 15, 2013
Project No: 11239

Client:
Report No.:
Revision No.:

SST Wireless Inc.
11239-1E
0

- Test configuration for Harmonic measurement, installed in Tire1



Prepared by: LabTest Certification Inc.
Date Issued: February 15, 2013
Project No: 11239

Client:
Report No.:
Revision No.:

SST Wireless Inc.
11239-1E
0

- Test configuration for Unintentional measurement below 30MHz, installed in Tire3




Prepared by: LabTest Certification Inc.
Date Issued: February 15, 2013
Project No: 11239

Client:
Report No.:
Revision No.:

SST Wireless Inc.
11239-1E
0

- Tire1, installed EUT inside.



- Tire2, installed EUT inside.



Prepared by: LabTest Certification Inc.
Date Issued: February 15, 2013
Project No: 11239

Client:
Report No.:
Revision No.:

SST Wireless Inc.
11239-1E
0

- Tire3, installed EUT inside.



- EUT: installed on rim, Top View

