

## **Response to TCB Findings**

1. Please specify the label material

**The label material is metallized polyester.**

2. Please explain why AC line conducted emissions test was not conducted on the device.

**This device is powered by a pure DC supply (vehicle battery).**

3. There seems to be a cable connection between the receiver and the transmitter in the radiated emissions test set-up photo. Please clarify the purpose of this direct connection in terms of functionality.

**The cable you see is a service cable; it is used for the purpose of recharging the batteries of the transmitter and is not connected during normal operation**