




## APPENDIX 1 - PHOTOGRAPHS OF EUT

### EXTERNAL PHOTOGRAPHS OF EUT

Model: DAP-3310










**Model: WCB1105H10DX**








**Model: WCB1100H10DX**













**Model: AC-GTT-11N-D**







**Compliance Certification Services Inc.**


Report No.: T130322W11



Date of Issue: May 3, 2013





**Model: AC-GTT-11N-O**







**Compliance Certification Services Inc.**

Report No.: T130322W11



Date of Issue: May 3, 2013





**Model: WLO-12410N**







**Compliance Certification Services Inc.**

Report No.: T130322W11


Date of Issue: May 3, 2013





**Model: WLO-12400N**







**Compliance Certification Services Inc.**

Report No.: T130322W11

Date of Issue: May 3, 2013

