

- Radiated emissions setup photos at 13010 Sledge Road, Charlotte, NC.



- Radiated emissions setup photos at 14220 Sledge Road, Charlotte, NC.



Radiated emissions setup photos at 13406 Sledge Road, Charlotte, NC.



- **Radiated emissions setup photos at 13010 Sledge Road, Charlotte, NC.
Installation of the MV capacitive coupler on the MV line**



**Radiated emissions setup photos at 14220 Sledge Road, Charlotte, NC.
Installation of the overhead MV capacitive coupler on the MV line**



**Radiated emissions setup photos at 13406 Sledge Road, Charlotte, NC.
Installation of the overhead MV capacitive coupler on the MV line**

