


8. Photographs of test setup

Photograph 1: Set-up for Conducted Emissions at Antenna Port



Prüfbericht - Nr.:
Test Report No.:

12307454 001

Seite 69 von 76
Page 69 of 76

Photograph 2: Set-up for Radiated Emission, EUT Configuration X-Axis



Photograph 3: Set-up for Radiated Emission, EUT Configuration Y-Axis




Photograph 4: Set-up for Radiated Emission, EUT Configuration Z-Axis




Photograph 5: Set-up for AC Mains Conducted Emission of Transmitter, Front View




Photograph 6: Set-up for AC Mains Conducted Emission of Transmitter, Rear View



Photograph 7: Set-up for Radiated Emission of Transmitter, Front View



Photograph 8: Set-up for Radiated Emission of Transmitter, Rear View



Photograph 9: Set-up for Radiated Emission of Receiver, Front View



Photograph 10: Set-up for Radiated Emission of Receiver, Rear View

