


Prüfbericht - Nr.: 15059842 001
Test Report No.:

Seite 64 von 67
Page 64 of 67

7. Photographs of the Test Setup


Photograph 1: Set-up for Conducted RF test at Antenna Port



Prüfbericht - Nr.: 15059842 001
Test Report No.:

Seite 65 von 67
Page 65 of 67

Photograph 2: Set-up for Radiated Emission, 30MHz-1000MHz



Photograph 3: Set-up for Radiated Spurious Emission, 1G-18GHz

