

ID: TLK-EVERE-A37X

REPORT NO: EF/2005/90018 DATE: Nov. 03, 2005



APPENDIX 1

PHOTOGRPHS OF SET UP



ID: TLK-EVERE-A37X

REPORT NO: EF/2005/90018 DATE: Nov. 03, 2005



Radiated Emission Set up Photo



Radiated Emission Set up Photo (Audio-in Mode)



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan. / 台北縣五股工業區五工路134號
t (886-2) 2299-3939

f (886-2) 2298-2698

www.sgs.com.tw





ID: TLK-EVERE-A37X

REPORT NO: EF/2005/90018 DATE: Nov. 03, 2005



Conducted Emission Set up Photo





The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan. / 台北縣五股工業區五工路134號
t (886-2) 2299-3939

f (886-2) 2298-2698

www.sgs.com.tw