

Report Number:
Issue Date:
Customer:
Model:



Figure 2a. Photograph of Spurious Radiation Test Setup, (Front View)

Report Number:
Issue Date:
Customer:
Model:




Figure 2b. Photograph of Spurious Radiation Test Setup, Rear View.