


PHOTOGRAPHS OF THE TEST CONFIGURATION



AC Power Conducted Emissions







Unwanted Emissions below 1 GHz





1Tx Dipole












1Tx PIFA












2Tx Dipole









2Tx PIFA












Unwanted Emissions above 1 GHz


1Tx Dipole









1Tx PIFA





2Tx Dipole





2Tx PIFA

