


Report No.: EED32N810192 Page 20 of 31

## PHOTOGRAPHS OF TEST SETUP

Test Model No.: BP3GY1-2N



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32N810192 Page 21 of 31



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.

