




## Appendix D - Product Photos



**Antenna Position:**




### Appendix E - Test Setup Photos



**Right Cheek**




**Right Tilted**




**Left Cheek**




**Left Tilted**



Front Face with 0cm Gap



Rear Face with Holster 0cm Gap



Rear Face with 1.5cm Gap



***Appendix F - Original Report***

Please refer to Sporton report number FA762206-2-2-01 as below.