

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission
(Below 1 GHz)



Photo 1




Photo 2

Radiated Spurious Emission
(Above 1 GHz)




Photo 1




Photo 2

Worst Case Position

Below 1 GHz (Horizontal: Y-axis/ Vertical: Y-axis)
Above 1 GHz (Horizontal: X-axis/ Vertical: X-axis)

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report