

APPENDIX 3: Photographs of Test Setup

Test setup (Overall view)




Photo 1






Photo 2

Test setup (axis)


X-axis



Y-axis





Z-axis



The photos show the cable connecting the EUT and SG removed.

Internal Photo



End of Report