

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission


Front



Below 30 MHz



30 MHz – 1 GHz




Above 1 GHz




Pre-check of Worst Case Position


X-axis




Y-axis



Z-axis



Antenna terminal conducted tests



End of Report