

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc.

Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone : +81 478 88 6500

Facsimile : +81 478 82 3373

Radiated Spurious Emission



Photo 1




Photo 2

Radiated Spurious Emission




Photo 1





Photo 2

Worst Case Position
(Horizontal: Z-axis/ Vertical: Z-axis)


X-axis



Y-axis



Z-axis



End of Report