

APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission



Photo 1




Photo 2

Worst Case Position

Test Range		Horizontal	Vertical
Below 1 GHz		X-axis	X-axis
Above 1 GHz	Carrier	Y-axis	Y-axis
	Harmonics	Z-axis	X-axis

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1



Photo 2

End of Report