

INTERTEK TESTING SERVICE


Report No: HK12080406-3

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)

Model: 89389



INTERTEK TESTING SERVICE


Report No: HK12080406-3

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Left View)

Model: 89389



INTERTEK TESTING SERVICE

Report No: HK12080406-3

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Right View)

Model: 89389

