
APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 1





Photo 2

Worst Case Position


Below 1 GHz (Horizontal: X-axis/ Vertical:X-axis)

Above 1 GHz (Horizontal: X-axis/ Vertical:Z-axis)

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1



Photo 2

End of Report