

APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission




Photo 1




Photo 2


Worst Case Position

Test Range	Horizontal	Vertical
Below 1 GHz	Z-axis	Y-axis
Above 1 GHz	X-axis	X-axis


X-axis



Y-axis



Z-axis



End of Report