
APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1





Photo 2


Radiated Spurious Emission



Front




Rear (up to 1 GHz)




Rear (above 1 GHz)

Pre-check of the Worst Case Position

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report