


**Annex B.iii. Photograph: Test Setup Photo**

 A photograph showing a wooden table in a test chamber. On the table, there is a small electronic device connected to a power source and some test equipment. The background shows the interior of the test chamber with various cables and equipment.	 A photograph showing a side view of the conducted emissions test setup. It features a wooden table with a power strip and a device under test. The setup is positioned near a metal wall and a power distribution unit.
Conducted Emissions Test Setup Front View	Conducted Emissions Test Setup Side View
 A photograph showing the radiated spurious emissions test setup below 1GHz. It features a white table with a device under test and a power source. The table is positioned in a test chamber with a grid of absorbers on the walls.	 A photograph showing the radiated spurious emissions test setup above 1GHz. It features a white table with a device under test and a power source. The table is positioned in a test chamber with a grid of absorbers on the walls.
Radiated Spurious Emissions Test Setup Below 1GHz	Radiated Spurious Emissions Test Setup Above 1GHz