



6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emissions, AC Mains



Photograph 2: Set-up for Co-Located Radiated Spurious Emissions, below 1GHz



Prüfbericht - Nr.: CN23WJ7J 002
Test report no.

Seite 29 von 30
Page 29 of 30

Photograph 3: Set-up for Co-Located Radiated Spurious Emissions, above 1GHz

