




Bottom View
“Close Up on Reverse Side of Transmitter”



Removing Board from Housing




*Bottom View
“Back of Touch Screen”*




8 RANCHO CIRCLE, LAKE FOREST, CA 92630

T (949)454-8295
F (949)829-6903


AegisLabsInc.com



Bottom View of Board



*Bottom View of Board
“Close up of Transmitter”*



Bottom View of Board
“Close up of Transmitter – Shield Removed”