



Exhibit 07A

Test Setup Photos

Testing of the rescueME PLB3 (PLB-450) in accordance with
Cospas-Sarsat T.007

25th January 2023



Antenna Characteristics



Figure 1 - Antenna Characteristics Configuration 1



Figure 2 – Showing plastic container for 'Wet' configuration




Figure 3 – Antenna Characteristics Configuration 4

Satellite Qualitative and PAT PAT Tests



Figure 4 - Satellite Qualitative and A.3.8.2 - Configuration 7



Figure 5 - Satellite Qualitative and A.3.8.2 - Configuration 8



Figure 6 - A.3.8.2 - Configuration 7 (Wet)

Moffset Test



Figure 7 - A.3.8.8.1 Configuration 8



Figure 8 - A.3.8.8.1 Configuration 7

UTC Test



Figure 9 - A.3.8.8.2 Configuration 7



Figure 10 - A.3.8.8.2 Configuration 8