

INTERTEK TESTING SERVICE


Report No: HK10110996-2

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)

Model : TS03RC



INTERTEK TESTING SERVICE


Report No: HK10110996-2

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)

Model : TS03RC



INTERTEK TESTING SERVICE

Report No: HK10110996-2

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)

Model : TS03RC

