
INTERTEK TESTING SERVICE


Report No: 13061080HKG-002

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)

Model: OP0118-13




Configuration Photographs

Worst-Case Line-Conducted Emissions

(Rear View)

Model: OP0118-13



Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)

Model: OP0118-13

