

2762IC11

1. APPENDIX I & II:
 - a. Item 15: Please uncheck Receiver. [Done.](#)
 - b. Item 16: Please match the Emission Designator to the occupied bandwidth 12M3FXD. [Done.](#)
 - c. Item 18: This device is measured in watts. Please mark this N/A. [Done.](#)
 - d. Item 21: Receiver data is not applicable. Please mark this N/A. [Done.](#)
2. TEST REPORT: Page 7: RSS-210 at the bottom of the page lists Issue 7. Please correct to Issue 8. [Done.](#)

2757UC11

3. RECEIVER: The receiver is a separate device, and will need its own certification. Please remove it from this filing and submit a separate filing. We will list where it needs to be removed below.
4. EXTERNAL PHOTOS: Please remove the photos of the receiver. [Done.](#)
5. MPE REPORT: Please remove the photos of the receiver. [Done.](#)
6. TEST SETUP PHOTOS: Please remove the photos of the receiver. [Done.](#)
7. BLOCK DIAGRAM: Please list the frequencies of the clocks and oscillators. [Done.](#)
8. USER MANUAL: Please add the following statement to the user manual: [Done.](#)
The antenna(s) used for this transmitter must be installed to provide a separation distance of at least 20 cm from all persons.
9. TEST REPORT:
 - a. Pages 22-23: Please remove the receiver spurious information. [Done.](#)
 - b. Pages 25-26: Please indicate that the level is in dBuV/m. [Done.](#)
 - c. Page 40: The screen capture of the spectrum analyzer has an asterisk "*" in the upper right hand corner. This usually indicates a measurement error. Please explain or revise. [New plot recaptured and included in test report.](#)
 - d. Page 46: Please remove the photo of the receiver. [Done.](#)